

3ATI & IV81A Repair Services

OPTICAL DISPLAY engineering

FAA Repair Station #09DR363Y / EASA 145.6402

"Perfecting Avionic LCD Repairs"



"State of the Art" repair facility

Optical Display Engineering...

Developed FAA approved repair procedures for the LCD display modules that fit the Honeywell/Bendix, Thales, GE and Honeywell/ACSS VSI/TCAS units.

Vertical Speed Indicator

Traffic Collision Avoidance Systems



All our screen repairs come with an industry leading 2 year warranty and advance *Flat Rate Exchange.

Type	OEM Part	MFG Part	Display OEM	LRU Part Number	Manufacturer	LRU Function
3ATI	30060110-0501	TFD32W02	Toshiba	066-50001-xxxx	Honeywell/Bendix	TCAS / Vertical Speed Indicator
3ATI	30060110-0502	TFD32W02/A	Toshiba	066-50001-xxxx	Honeywell/Bendix	TCAS / Vertical Speed Indicator
3ATI	30060110-0504	TFD32W20B	Toshiba	066-50001-xxxx	Honeywell/Bendix	TCAS / Vertical Speed Indicator
3ATI	30060110-0506	TFD32W20C	Toshiba	066-50001-xxxx	Honeywell/Bendix	TCAS / Vertical Speed Indicator
3ATI	30060110-0508	04320073-0005	Honeywell	066-50001-xxxx	Honeywell/Bendix	TCAS / Vertical Speed Indicator
3ATI	96154439	TFD32W10	Toshiba	457400(*)	Thales	TCAS / Vertical Speed Indicator
3ATI	96154439	TFD32W10/A	Toshiba	457400(*)	Thales	TCAS / Vertical Speed Indicator
3ATI	F1252766	F1252766	Thales	457400(*)	Thales	TCAS / Vertical Speed Indicator
3ATI	E19947BA	E19947BA	Thales	457400(*)	Thales	TCAS / Vertical Speed Indicator
3ATI	E19947GA	E19947GA	Thales	457400(*)	Thales	TCAS / Vertical Speed Indicator
3ATI	71258-0002	TFD32W02B	Toshiba	133-380022-29 / 31	GE/Smiths	EID / Electronic Instrument Display
3ATI	40-647-619	TFD32W02B	Toshiba	133-380022-29 / 31	GE/Smiths	EID / Electronic Instrument Display
3ATI	71268-0001	996-0401-08	Planar	133-380022-29 / 31	GE/Smiths	EID / Electronic Instrument Display
3ATI	40-647-631	996-0401-08	Planar	133-380022-29 / 31	GE/Smiths	EID / Electronic Instrument Display

**if rotatable stock is available*